



AEROSEAL

Case Study

MEZ-AEROSEAL

Motel one

» Sealing during installation and reducing total leakage by approx. 92.1%. «

Motel one

Location: 38 TAMKA STREET, WARSAW, Poland
Date: -
MEZ-AEROSEAL Partner: Energy Air Sp. z o.o
Executing company: -
Result: -



Smell



Noise



Energy efficiency



Air tightness



Indoor air quality

Description

Motel One, this budgetary and designer hotel is located near the Vistula River in Warsaw's Downtown. Was opened in July 2019, and the opening ceremony was held on 24 October. Sealing using AEROSEAL® technology included two exhaust systems (W1 and W2) for the connection of 360 hotel bathrooms and the N4 supply air shaft.

Before sealing, the ventilation ducts did not meet any tightness class.

Successful sealing

With our successful MEZ-AEROSEAL partner network we achieve great success again and again.

The change in leakages

Before sealing

- ATC 7

After sealing

-

Reduction

- (W1) 93,5%
- (W2) 90,3%
- (N4) 92,7%



www.mez-technik.com



info@mez-technik.de



+49 (7072) 600980